

EXTOLL

Problem

New ASICs in the SDV require a new extoll library.

Workaround

Try to add the following to your LD_LIBRARY_PATH:

For the KNLs:

/direct/Software/Extoll/ASIC2/extoll2_knc/lib

(don't be confused, KNL's the "same" architecture like KNC, so no rebuild is necessary)

For the Haswells:

/direct/Software/Extoll/ASIC2/extoll2/lib