

## **Wikiprint Book**

**Title: EXTOLL**

**Subject: DEEP - Public/User\_Guide/PaS**

**Version: 71**

**Date: 09.05.2025 20:56:37**

## Table of Contents

<b>EXTOLL</b>	<b>3</b>
Problem	3
Workaround	3

## EXTOLL

### Problem

New ASICs in the SDV require a new extoll library.

### Workaround

Try to add the following to your LD\_LIBRARY\_PATH:

For the KNLs:

/direct/Software/Extoll/ASIC2/extoll2\_knc/lib

(don't be confused, KNL's the "same" architecture like KNC, so no rebuild is necessary)

For the Haswells:

/direct/Software/Extoll/ASIC2/extoll2/lib