# Wikiprint Book

Title: Public/User\_Guide/PaS

Subject: DEEP - Public/User\_Guide/PaS

Version: 70

Date: 02.05.2024 17:49:59

# **Table of Contents**

Detected HW and node issues	3
CM nodes	3
DAM nodes	3
ESB nodes	3
SDV nodes	3
Software issues	3
Modular jobs failing	3

This page is intended to give a short overview on known issues and to provide potential solutions and workarounds to the issues seen.

Last update: 2020-09-22

## GPFS issues occured, user login currently not possible !

To stay informed, please refer to the <u>News page</u>. Also, please pay attention to the information contained in the "Message of the day" displayed when logging onto the system.

# Detected HW and node issues

#### CM nodes

- · dp-cn[09,10]: nodes currently reserved for special use case during working hours
- dp-cn11: node was not responding (#2426)
- dp-cn24: thermal trip asserted (<u>#2443</u>, <u>#2306</u>)
- dp-cn41: node not responding (<u>#2477</u>)

# DAM nodes

- dp-dam03: node currently reserved for special use case (#2242)
- dp-dam04: showing low streams performance (<u>#2401</u>)
- dp-dam05: node currently reserved for special use case
- dp-dam07: showing problems with its FPGA (#2353)
- dp-dam[09,10]: nodes currently reserved for special use case during working hours

## ESB nodes

- dp-esb02: energy meter reading issues
- dp-esb03: energy meter reading issues (<u>#2466</u>)
- dp-esb11: wrong GPU Link Speed detected (#2358)
- dp-esb23: MCE problems (<u>#2350</u>)
- dp-esb24: CentOS8 Testbed (#2396)
- dp-esb28: no access to bmc (#2430)
- dp-esb33: no access to bmc (#2429)
- dp-esb38: no access to bmc
- dp-esb39: energy meter reading issues (#2432)
- dp-esb52: energy meter reading issues (#2433)
- dp-esb71: energy meter reading issues (#2432)
- dp-esb73: energy meter reading issues (#2433)

## SDV nodes

- deeper-sdv01: node reachable via nework, but marked as down in SLURM
- nfgw[01,02]: node reachable via nework, but marked as down in SLURM
- knl01: NVMe issues (<u>#2011</u>)

## Software issues

# Modular jobs failing

- · users reported failing jobs that are doing MPI on more than one module using the gateways
- the problem is being investigated